

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AS228
West
1/4-1/2
0.351 mi.
1851 ft.

LANE DISTRIBUTING CORP.
CROPSEY AVE & HART PLACE
BROOKLYN, NY 11224

NY CBS
NY CBS AST
NY Spills

S102146563
N/A

Site 5 of 7 in cluster AS

Relative:
Higher

CBS:

Actual:
9 ft.

Name: LANE DISTRIBUTING CORP.
Address: CROPSEY AVE & HART PLACE
City,State,Zip: BROOKLYN, NY 11224
CBS Number: 2-000077
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 585841.07001
UTMY: 4492698.88998

CBS AST:

CBS Number: 2-000077
ICS Number: 2-700370
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: A
Telephone: (718) 966-0700
Facility Town: NEW YORK CITY
Region: STATE
Expiration Date: 07/05/1993
Total Capacity of All Active Tanks(gal): 0
Operator: RONALD BRANDENBURG
Emergency Contact: RONALD BRANDENBURG
Emergency Phone: (201) 348-8323
Owner Name: LANE DISTRIBUTING CORP.
Owner Address: CROPSEY AVE & HART PLACE
Owner City,St,Zip: BROOKLYN, NY 11224
Owner Telephone: (718) 966-0700
Owner Type: Corporate/Commercial
Owner Sub Type: Not reported
Mail Name: LANE DISTRIBUTING CORP.
Mail Contact Addr: CROPSEY AVE & HART PLACE
Mail Contact Addr2: Not reported
Mail Contact Contact: RONALD BRANDENBURG
Mail Contact City,St,Zip: BROOKLYN, NY 11224
Mail Phone: (718) 966-0700

Tank Id: A & B
CAS Number: 7681529
Federal ID: Not reported
Tank Status: 0
Install Date: 03/84
Tank Closed: 10/91
Capacity (Gal): 8500
Chemical: Sodium hypochlorite
Tank Location: Indoors, Aboveground
Tank Type: Fiberglass reinforced plastic [FRP]
Total Tanks: 0
Tank Secret: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Tank Secondary Containment: None
Tank Error Status: No Missing Data
Date Entered: 07/05/1989
Certified Date: 06/13/1991
Substance: Single Hazardous Substance on DEC List
Internal Protection: None
External Protection: None
Pipe Location: Aboveground
Pipe Type: Double Walled Fiberglass
Pipe Internal: None
Pipe External: None
Pipe Flag: None
Leak Detection: None
Overfill Protection: None
Haz Percent: 100
Last Test: Not reported
Due Date: Not reported
SWIS Code: 6101
Lat/Long: Not reported
Is Updated: False
Renew Date: 03/15/91
Is It There: False
Delinquent: False
Date Expired: 07/05/93
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: False
Pre-Printed Renewal App Last Printed: 03/15/1991

SPILLS:

Name: CROPSEY AVE & HART PLACE
Address: CROPSEY AVE & HART PLACE
City, State, Zip: BROOKLYN, NY
Spill Number/Closed Date: 9302816 / 1993-06-02
Facility ID: 9302816
Facility Type: ER
DER Facility ID: 147965
Site ID: 176055
DEC Region: 2
Spill Cause: Unknown
Spill Class: D4
SWIS: 2401
Spill Date: 1993-06-02
Investigator: CAMMISA
Referred To: Not reported
Reported to Dept: 1993-06-02
CID: Not reported
Water Affected: Not reported
Spill Source: Vessel
Spill Notifier: Citizen
Cleanup Ceased: 1993-06-02
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1993-06-07
Spill Record Last Update: 1993-07-19

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: ""

Remarks: "THE SEA QUEEN 65FT. BEAT LEAKING OIL - PEOPLE ARE STRIPPING IT- HALF IN + OUT OF WATER - SHEEN ON SURFACE - DURING LIGH TIDE OIL COMES FROM HULL USCG NOTIFIED."

All Materials:

Site ID: 176055
Operable Unit ID: 984822
Operable Unit: 01
Material ID: 399922
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported